

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2013 Levee Inspection Results**

**Reclamation District No. 2058 Pescadero**

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)				

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*  
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments


**Flood Control Project Maintenance  
Levee Inspections**

**Unit Cover Sheet**

**Spring 2013 Levee Inspection Results**

**Reclamation District No. 2058 Pescadero**

Waterway			Bank	Unit Miles
Unit No. 01 Paradise Cut			Left	6.71
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	05/22/2013 - 05/22/2013			
DWR Inspector	Maksim Khashchuk			
Accompanied By	Greg Pombo			

**Summer & Winter Inspections**

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

*The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.*

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location * + Rating + Ma	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
1				Flood Preparedness & Training	WS A Ma		°	°	6
DWR ID: DWR_RD2058_01_s_2013_6									
2				Emergency Supplies & Equipment	WS A Ma		°	°	7
DWR ID: DWR_RD2058_01_s_2013_7									
3				Operations & Maintenance Manuals	WS A Ma		°	°	9
DWR ID: DWR_RD2058_01_s_2013_9									
4	0.41	0.44		Vegetation	LS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes.	37.803834 ° -121.415720 °	37.803411 ° -121.415268 °	10 Y
DWR ID: DWR_RD2058_01_s_2013_10									
5	0.42	0.42		Vegetation	WS M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Thick vegetation at this point, needs to be removed.	37.803813 ° -121.415578 °	37.803813 ° -121.415578 °	8 Y
DWR ID: DWR_RD2058_01_s_2012_8									
6	0.73	0.73		Encroachments	LS A/W En	PI : Pipe	37.801952 ° -121.411002 °	37.801952 ° -121.411002 °	3 Y
DWR ID: DWR_RD2058_01_f_2012_3									
7	0.78	4.03		Vegetation	LS M Ma	V1 : Control annual grass and weeds on the levee slopes and easements.	37.801743 ° -121.410072 °	37.788987 ° -121.360600 °	11
DWR ID: DWR_RD2058_01_s_2013_11									
8	0.96	0.96		Encroachments	LS C Ma	PR : Prunings	37.801428 ° -121.406495 °	37.801428 ° -121.406495 °	4
DWR ID: DWR_RD2058_01_f_2012_4									
9	1.24	1.24		Encroachments	CRA/W En	PI : Pipe	37.802314 ° -121.401984 °	37.802314 ° -121.401984 °	22 Y
DWR ID: DWR_RD2058_01_s_2012_22									
10	1.69	1.72		Vegetation	WS M Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Removal of this type of vegetation is currently prohibited by FWS.	37.804158 ° -121.394169 °	37.804329 ° -121.393612 °	961
DWR ID: DWR_RD2058_01_s_2012_961									

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
11	2.15	2.15	Supplemental	DWR Erosion Survey	WS	M	Inspector Comments: 07/31/2012: Site was visited on 07/26/2012. No significant change observed. A new vertical pipe was installed and concrete blocks left on the site. Dense vegetation around the site. No signs of new leaks or spill from the siphon breaker. 09/02/2011: Site was not visited due to the time limit. 09/22/2010: No significant changes observed. Vegetation downstream, upstream and on the lower slope of the site have been recently sprayed. These areas were also fenced off during the site visit, making it difficult for us to examine the condition of the lower slope. Possible leak or spill from the siphon breaker is creating notches along the slope and developing into a headward erosion. If the problem continues, it will erode the slope and fully expose the pipe to outside elements. 07/23/2009: A possible leak or spill from a siphon breaker is eroding the slope and developing into a headward erosion; a portion of the buried pipe is exposed; the lower slope seems to be lined with chunks of concrete debris or other rock material. [2012 Site ID:RD2058U01RM1.78]	37.803769 ° -121.386341 °	37.803769 ° -121.386341 °	1 Y
12	2.15	2.15		Encroachments	CRA/W	PI : Pipe		37.803910 ° -121.386295 °	37.803910 ° -121.386295 °	23 Y
13	2.42	2.42		Vegetation	LS A/W	V4 : Elderberries are blocking visibility and flood fight capability.	Inspector Comments: Elderberry growing on landside toe.	37.802782 ° -121.381413 °	37.802782 ° -121.381413 °	16 Y
14	2.64	2.64		Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability.	Inspector Comments: Elderberry on water side slope.	37.801962 ° -121.377684 °	37.801962 ° -121.377684 °	63 Y
15	2.66	2.66		Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability.		37.801876 ° -121.377291 °	37.801876 ° -121.377291 °	64
16	2.67	2.67		Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability.		37.801823 ° -121.377068 °	37.801823 ° -121.377068 °	65
17	2.76	2.76		Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability.		37.801497 ° -121.375586 °	37.801497 ° -121.375586 °	66
18	2.89	2.89		Encroachments	WSA/W	PI : Pipe		37.800894 ° -121.373135 °	37.800894 ° -121.373135 °	24 Y
19	3.41	3.41		Encroachments	CRA/W	PI : Pipe	Inspector Comments: Drainage discharge.	37.796421 ° -121.366254 °	37.796421 ° -121.366254 °	27
20	3.57	3.57		Vegetation	LS A/W	V4 : Elderberries are blocking visibility and flood fight capability.		37.794396 ° -121.364944 °	37.794396 ° -121.364944 °	68

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
21	3.76	3.76		Vegetation	WS Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Flagged bushes obstructing visibility and access	37.791856 ° -121.363514 °	37.791856 ° -121.363514 °	974
DWR ID: DWR_RD2058_01_s_2012_974									
22	3.85	3.85		Vegetation	WSA/W Ob	V8 : Environmental Requirements. Inspector Comments: Revegetation site.	37.790807 ° -121.362905 °	37.790807 ° -121.362905 °	20 Y
DWR ID: DWR_RD2058_01_s_2012_20									
23	4.01	4.01		Vegetation	LS Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry on landside hinge point.	37.789128 ° -121.361042 °	37.789128 ° -121.361042 °	26 Y
DWR ID: DWR_RD2058_01_s_2012_26									
24	4.01	4.01		Vegetation	WSA/W Ma	V4 : Elderberries are blocking visibility and flood fight capability.	37.789096 ° -121.360966 °	37.789096 ° -121.360966 °	69
DWR ID: DWR_RD2058_01_s_2012_69									
25	4.36	4.36		Vegetation	WSA/W Ma	V4 : Elderberries are blocking visibility and flood fight capability.	37.789794 ° -121.354883 °	37.789794 ° -121.354883 °	71
DWR ID: DWR_RD2058_01_s_2012_71									
26	4.49	4.53	Supplemental	DWR Erosion Survey	WS Ma	Inspector Comments: 07/26/2012: The site has been visited, and no significant change has been observed. 09/02/2011: This site was not visited due to the time limit. 09/22/2010: No significant changes observed. Minor pocket erosions are lined at the lower bank. Two large Oak and Willow trees are on midslope and bench. The remaining bench was re-measured and found to be approximately 10 feet. There was no indication of active erosion on site during the site visit. 08/05/2010: Recommended for annual assessment and monitoring of site during flood events, per CLRO. 07/23/2009: No major change observed since last visit; site is a 200-ft. long near-vertical berm erosion; recommend annual assessment and monitoring of erosion site, per CLRO CES Evaluation 2008 Report; Site # is the same site previously reported as RM4.0,LM4.51; previously rated "U". 09/10/2008: Two large trees (2-3' DBH) with partial roots exposed. 2007: Visited site 03/13/2007. [2012 Site ID:RD2058U01RM3.97]	37.789810 ° -121.352490 °	37.789810 ° -121.352490 °	2 Y
DWR ID: DWR_RD2058_01_s_2013_2									
27	5.16	5.16		Encroachments	LS En	RA : Ramp Inspector Comments: New Ramp construction Connecting Dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.	37.783102 ° -121.345682 °	37.783102 ° -121.345682 °	29 Y
DWR ID: DWR_RD2058_01_s_2012_29									
28	5.37	5.37		Encroachments	LS En	RA : Ramp Inspector Comments: Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.	37.782268 ° -121.342257 °	37.782268 ° -121.342257 °	30 Y
DWR ID: DWR_RD2058_01_s_2012_30									

* Location	** Rating	+ Issue Type
LS : Land Side	A : Acceptable	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable	En : Enforcement
	N : Not Inspected/Rated	
	C : Corrected	
	A/W : Acceptable but Monitor & Maintain	

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location *	Rating ** +	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
29	6.06	6.06		Animal Control	WS	M	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.775015 ° -121.335233 °	37.775015 ° -121.335233 °	5 Y

DWR ID: DWR\_RD2058\_01\_f\_2012\_5

<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	4
Start Levee Mile	0.41
End Levee Mile	0.44
Location	Land Side
Category	
Item	Vegetation

View of the vegetation on the landside levee slope.

mkhashch\_s\_20130522\_743.JPG



Levee Mile Report Line	5
Start Levee Mile	0.42
End Levee Mile	0.42
Location	Water Side
Category	
Item	Vegetation

11/08/2011 Thick brush in this area needs to be taken back to 20' from hinge point.

mkhashch\_s\_20130225\_383.jpg



Levee Mile Report Line	6
Start Levee Mile	0.73
End Levee Mile	0.73
Location	Land Side
Category	
Item	Encroachments

View of discharge pipe on landside slope.

mkhashch\_s\_20130225\_380.JPG



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	9
Start Levee Mile	1.24
End Levee Mile	1.24
Location	Crown
Category	
Item	Encroachments

Drainage discharge to Paradise Cut.

mkhashch\_s\_20130225\_386.jpg



Levee Mile Report Line	11
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Close look at the site. Note the concrete blocks and vegetation.

mkhashch\_s\_20130225\_374.jpg



Levee Mile Report Line	11
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view of siphon breaker.

mkhashch\_s\_20130225\_375.jpg



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable  N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2013

### Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	12
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Crown
Category	
Item	Encroachments

Drainage discharge to Paradise Cut.

mkhashch\_s\_20130225\_387.jpg



Levee Mile Report Line	13
Start Levee Mile	2.42
End Levee Mile	2.42
Location	Land Side
Category	
Item	Vegetation

03/28/2012 Large elderberry bush on landside slope.

mkhashch\_s\_20130225\_384.jpg



Levee Mile Report Line	14
Start Levee Mile	2.64
End Levee Mile	2.64
Location	Water Side
Category	
Item	Vegetation

03/28/2012 Large elderberry bush located on waterward slope.

mkhashch\_s\_20130225\_396.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	18
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Water Side
Category	
Item	Encroachments

Irrigation intake from Paradise Cut.

mkhashch\_s\_20130225\_388.jpg



Levee Mile Report Line	22
Start Levee Mile	3.85
End Levee Mile	3.85
Location	Water Side
Category	
Item	Vegetation

11/08/2011 Revegetation site, cannot trim or cut vegetation in this area.

mkhashch\_s\_20130225\_385.jpg



Levee Mile Report Line	23
Start Levee Mile	4.01
End Levee Mile	4.01
Location	Land Side
Category	
Item	Vegetation

Elderberry bushes on landside slope.

mkhashch\_s\_20130225\_389.JPG



<b>* Location</b> LS : Land Side WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	26
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a pocket erosion site. Vegetation has developed and covered the erosion.

mkhashch\_s\_20130225\_376.jpg



Levee Mile Report Line	26
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a the erosion near a tree

mkhashch\_s\_20130225\_377.jpg



Levee Mile Report Line	26
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a the erosion near a tree

mkhashch\_s\_20130225\_378.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2013

### Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	26
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a the erosion near a tree

mkhashch\_s\_20130225\_379.jpg



Levee Mile Report Line	27
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	
Item	Encroachments

11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

mkhashch\_s\_20130225\_390.jpg



Levee Mile Report Line	27
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	
Item	Encroachments

11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

mkhashch\_s\_20130225\_391.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement



**Flood Control Project Maintenance  
Levee Inspections**

## Levee Inspection Report By Mile - Spring 2013

### Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	27
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	
Item	Encroachments

Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

mkhashch\_s\_20130225\_392.JPG



Levee Mile Report Line	28
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	
Item	Encroachments

11/08/2011 Photo shows existing middle ramp to the levee which has been raised.

mkhashch\_s\_20130225\_393.jpg



Levee Mile Report Line	28
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	
Item	Encroachments

11/08/2011 Photo shows view from the levee looking to the left of the middle ramp.

mkhashch\_s\_20130225\_394.jpg



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2013**

**Reclamation District No. 2058 Pescadero**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	05/22/2013 05/22/2013	Maksim Khashchuk

Levee Mile Report Line	28
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	
Item	Encroachments

Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

mkhashch\_s\_20130225\_395.JPG



Levee Mile Report Line	29
Start Levee Mile	6.06
End Levee Mile	6.06
Location	Water Side
Category	
Item	Animal Control

View of rodent burrows on waterside slope.

mkhashch\_s\_20130225\_382.JPG



**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
N : Not Inspected/Rated  
C : Corrected  
A/W : Acceptable but Monitor & Maintain

**+ Issue Type**

Ma : Maintenance Deficiency  
Ob : Design & System Obsolescence  
En : Enforcement